

# VISIONSAFE CORPORATION

## EVAS<sup>®</sup> Services Policy and Price Sheet

Effective: 01 February 2021

Service		Description of Item and/or Service	Price*
1	Biennial Service	Unit received up to 3 months after the Base Service Date as shown on the face of the EVAS <sup>®</sup> unit	\$815
2	Re-set Base Date	Unit received for Biennial Service 4-12 months after the Base Service Date as shown on the face of the EVAS <sup>®</sup> unit	\$200 + item 1
3	Non-Standard Service	Unit received with evidence of liquid contamination, exposure of internal parts, customer damage to unit, or > 12 months after the Base Service Date as shown on the face of the EVAS <sup>®</sup> unit - replace multiple parts as necessary and perform Biennial Service.  <b>NOTE: If unit is not serviceable, it will be returned to owner unserviced, at no charge.</b>	\$3,370
4	120 Month Rebuild	Replace IVU, Battery Pack, and other parts as needed, to conform to current configuration.	\$6,735
5	Inspected	External Inspection, Internal inspection and functional testing	\$400

\*CPI information obtained from the [Bureau of Labor Statistics](https://www.bls.gov/)