

EVAS® Services Policy and Price Sheet

Effective: 01 January 2022

Service		Description of Item and/or Service	Price*
1	Biennial Service	Unit received up to 3 months after the Base Service Date as shown on the face of the EVAS® unit	\$840
2	Re-set Base Date	Unit received for Biennial Service 4-12 months after the Base Service Date as shown on the face of the EVAS® unit	\$206 + item 1
3	Non-Standard Service	Unit received with evidence of liquid contamination, exposure of internal parts, customer damage to unit, or > 12 months after the Base Service Date as shown on the face of the EVAS® unit - replace multiple parts as necessary and perform Biennial Service. NOTE: If unit is not serviceable, it will be returned to owner unserviced, at no charge.	\$3,472
4	120 Month Rebuild	Replace IVU, Battery Pack, and other parts as needed, to conform to current configuration.	\$6,937
5	Inspected	External Inspection, Internal inspection and functional testing	\$412

^{*}CPI information obtained from the <u>Bureau of Labor Statistics</u>