

# VISIONSAFE CORPORATION

## EVAS<sup>®</sup> Services Policy and Price Sheet

Effective: 01 January 2024

| Service |                      | Description of Item and/or Service   | Price*  |
|---------|----------------------|--|---------|
| 1       | Biennial Service     | Unit received up to 3 months after the Base Service Date as shown on the face of the EVAS <sup>®</sup> unit  | \$984   |
| 2       | Late Service         | Unit received for Biennial Service 4-12 months after the Base Service Date as shown on the face of the EVAS <sup>®</sup> unit  | \$1,809 |
| 3       | Non-Standard Service | Unit received with evidence of liquid contamination, exposure of internal parts, customer damage to unit, or > 12 months after the Base Service Date as shown on the face of the EVAS <sup>®</sup> unit - replace multiple parts as necessary and perform Biennial Service.<br><br><b>NOTE: If unit is not serviceable, it will be returned to owner unserviced, at no charge.</b> | \$4065  |
| 4       | 120 Month Rebuild    | Replace IVU, Battery Pack, and other parts as needed, to conform to current configuration.   | \$8122  |
| 5       | Inspected            | External Inspection, Internal inspection and functional testing  | \$483   |

\*CPI information obtained from the [Bureau of Labor Statistics](https://www.bls.gov/)